### **WEEKLY SUPPLEMENT NUMBER 26**

ISSUED BY: COMMANDER, THIRTEENTH COAST GUARD DISTRICToa(n) 915 Second Avenue, Seattle, Washington 98174-1067 Telephone (206) 220-7270 FAX # (206) 220-7285

#### BROADCAST NOTICES TO MARINERS BNMs)

This Local Notice to Mariners (LNM) includes information concerning waterways in the Thirteenth Coast Guard District promulgated by the following broadcasts:

BNM 0645-97 to 0669-97

## LIGHT LIST REFERENCE: COMDTINST M16502.6, Light List Volume VI, 1996 Edition

\*\*\*Electronic Bulletin Board Service: (703) 313-5910\*\*\*
300 to 28.8bps, 8 data bits, no parity, 1 stop bit

\*\*NIS watchstander, 24 hours a day at (703) 313-5900\*\*

\*INTERNET ADDRESS\*

HTTP://www.navcen.uscg.mil

or

FTP://ftp.navcen.uscg.mil

#### I. SPECIAL NOTICE

OREGON - WASHINGTON - APPLETON WASHINGTON - DIFFERENTIAL GLOBAL POSITIONING SYSTEM (DGPS)- BROADCAST BEACON - On Air -Test Phase -

A DGPS broadcast beacon has been established at Appleton, WA, in approximate position 45<sup>2</sup>46'53.0"N 121<sup>2</sup>19'33.0"W. The frequency for this site is 30**K**Hz with a range of 250 statute miles, broadcasting at a rate of 100 BPS. \*\*CAUTION\*\* This site transmits DGPS corrections. The carrier is modulated with a GPS correction (differential) signal, which may be used to greatly improve the accuracy of GPS. Mariners are urged not to rely solely on this DGPS site for navigation. This site is in the test phase and is not manned to detect errors and may be taken off air without prior notification. Aviation users are cautioned that DGPS corrections degrade the performance of some automatic direction finders used in aviation applications.

## WASHINGTON - LA PUSH - QUILLAYUTE RIVER - Entrance Flood Lights Established -

The Entrance Flood Lights have been restored to operation. These lights will be operated upon request. Users must contact Coast Guard StationQuillayute to activate the flood lights.

Chart 19480

# WASHINGTON - LA PUSH - QUILLAYUTE RIVER - WATERWAY ANALYSIS - Request for Comments -

The Coast Guard is conducting a analysis of Quillayute River (Light List Number 16075 to 16110) to evaluate the adequacy of the aids to navigation. Users of this waterway are invited to comment on the current system. All comments should be received by 25 July 1997 by: LCDRSchmitt, 3115 240h Ave NE, Redmond, WA 98053. Additionally if you would like to participate in a survey being conducted on this waterway, fill out the information sheet in enclosure (1) to this Local Notice to Mariners, and mail it to the appropriate address.

WASHINGTON - PUGET SOUND - WHIDBEY ISLAND - DIFFERENTIAL GLOBAL POSITIONING SYSTEM (DGPS) SITE - Off Air -

The DGPS site at Whidbey Island will be off air from 1000 local until 1400 local on 08 July 1997. The alternate period is 1000 local until 1400 local 09 July 1997. Mariners are reminded to use alternate means of navigation during this period.

 $WASHINGTON - PUGET\ SOUND - POINT\ ROBINSON - DIFFERENTIAL\ GLOBAL\ POSITIONING\ SYSTEM\ (DGPS)\ SITE - Off\ Air -$ 

The DGPS site at PointRobinson will be off air from 0900 local until 1300 local on 15 July 1997. The alternate period is 0900 local until 1300 local 16 July 1997. Mariners are reminded to use alternate means of navigation during this period.

PACIFIC OCEAN - OREGON - NATIONAL OCEANIC AND ATMOSPHERIC ADMINISTRATION (NOAA) - Temporary Buoy Deployment -

A data collection buoy will be established in approximate position 45 degrees 57 minutes north, 130 degrees 0 minutes west. This buoy will be orange and white, showing a Fl W (3) 3s. This buoy will be on station for approximately one year.

Chart 501

#### WASHINGTON - ELLIOTT BAY - FIREWORKS DISPLAY - Safety Zone -

The annual fireworks display in Elliott Bay will take place 04 July 1997. The Coast Guard Safety Zone Regulation for this event established a safety zone for all portions of Elliott Bay bounded by the following coordinates: 47²37′22″N, 122²22′06″W; thence to 47²37′06″N, 122²21′45″W; thence to 47²36′54″N, 122²22′05″W; thence to 47²37′09″N, 122²22′25″W; thence returning to the origin. This safety zone resembles a square centered around the barge from which the fireworks will be launched and begins 100 yards off MyrtEdwards Park. Floating markers will be placed by the sponsor of the fireworks display to delineate the boundaries of the safety zone. The zone is needed to protect vessels and their occupants from the safety hazards associated with viewing a fireworks display at close quarters. Entry into this zone is prohibited. This regulation becomes effective at 2130 local, 04 July 1997. During this time the Smith Cove East Anchorage will also be closed. The safety zone terminates at 2300 local, 04 July.

WASHINGTON - COMMENCEMENT BAY - FREEDOM FAIR AIRSHOW AND FIREWORKS DISPLAY - Safety Zone -

The annual Freedom Fair Airshow and Fireworks Display will take place in Commencement Bay, Tacoma, WA on 04 July 1996. A Coast Guard Safety Zone Regulation has been established for the event, and entry into the zone is prohibited unless authorized by the on scene Patrol Commander (PATCOM). The borders for the Safety Zone are 47²17'34.0"N 122²28'36.0"W thence to 47²17'06.0"N 122²27'40.0"W thence to 47²16'42.0"N 122²28'06.0"W thence to 47²17'10.0"N 122²29'02.0"W. This regulation becomes effective at 1400 local 04 July 1997 and will terminate at 0030 local, 05 July 1997 unless terminated sooner by PATCOM.

## WASHINGTON - BELLINGHAM BAY - FIREWORKS DISPLAY - Safety Zone -

The annual fireworks display in Bellingham Bay will take place on 04 July 1997. The Coast Guard Safety Zone Regulation for this event established a safety zone for all portions of Bellingham Bay bounded by the following coordinates: 48²44′09″N, 122²30′07″W; thence to 48²44′09″N, 122²29′57″W; thence to 48²44′02″N, 122²29′57″W; thence to 48²44′02″N, 122²30′07″W; thence returning to the origin. This safety zone resembles a square centered around the barge from which the fireworks will be launched. This regulation becomes effective from 1730 local to 2300 local, 04 July 1997.

# REPORT DEFECTS IN AIDS TO NAVIGATION TO THE NEAREST COAST GUARD UNIT

## I. SPECIAL NOTICE (continued)

WASHINGTON - LAKE WASHINGTON SHIP CANAL - LAKE UNION - FIREWORKS DISPLAY - Safety Zone -

The annual fireworks display in Lake Union will take place on 04 July 1997. The Coast Guard Safety Zone Regulation for this event established a safety zone for all portions of Lake Union bounded by the following coordinates: 47²38'32"N, 122²20'34"W; thence to 47²38'32"N, 122²19'48"W; thence to 47²38'10"N, 122²19'45"W; thence to 47²38'10"N, 122²20'24"W; thence returning to the origin. This safety zone begins 1,000 feet south of Gas Works Park and encompasses all waters from east to west for 2,500 feet. Floating markers will be placed by the sponsor of the fireworks demonstration to delineate the boundaries of the safety zone. This regulation becomes effective from 1730 local to 2300 local on 04 July 1997.

## CANADA - REGULATORY REQUIREMENTS FOR FOREIGN COMMERCIAL FISHING VESSEL ENTERING CANADIAN WATERS -

The Coastal Fisheries Protection regulations were amended 16 July 1996 to introduce new requirements for foreign commercial fishing vessels. Department of Fisheries and Oceans is reminding affected parties that these requirements are still in effect.

Please be advised that masters of foreign commercial fishing vessels must, as soon as reasonably possible, after entering Canadian waters:

- 1. Notify the Department of Fisheries and Oceans of the name, flag, state, location, route and destination of the vessel and of the circumstances under which it entered Canadian fisheries waters.
- 2. Ensure that all fishing gear on board the vessel is stowed below deck or otherwise removed from the place where it is normally used for fishing and placed where it is not readily available for fishing, and
- 3. Where requested by a Protection Officer, proceed to a specifilelocation so that a vessel inspection can be conducted

These requirements do not apply to foreign fishing vessels operating under a Canadian fishing license. In addition, they do not apply to United States sport fishing vessels conducting normal sport fishing activities.

Affected vessel masters can notify Department of Fisheries and Oceans on the following Marine Communications and Traffic Service channels 71, 11, or 22A. At that time, fishery officials will advise if a vessel inspection is required and provide information on gear stowage.

The primary reason for the requirements is conservation. Failure to comply with requirements is viewed as a serious offense. The Coastal Fisheries Protection Act specifies a maximum penalty of \$100,000.

## OREGON - WASHINGTON - COLUMBIA RIVER - Bridge Information -

The dual vertical lift spans of the Interstate 5 Bridges at Vancouver, Washington, river mile 106.5 need not open for the passage of vessels from 2000 local on 04 July to 0100 local 05 July 1997. This closure accommodates a public event.

Charts 18524 and 18526

## WASHINGTON - PUGET SOUND - Seismic Survey Operations -

The M/V ROBERT GRAY will be conducting seismic survey operations in Puget Sound from 23 June through 02 July 1997. M/V ROBERT GRAY will tow a streamer and other various equipment 250 meters in length behind the vessel. The vessel will be operating in the vicinity of the Traffic Separation Scheme. M/V ROBERT GRAY is

120 feet in length overall and will monitor VHF-FM Channels 13 AND 14. All other vessels should navigate with caution in the vicinity of the ROBERT GRAY.

#### WASHINGTON - PUGET SOUND - EAGLE HARBOR Remediation Project -

Remediation work will take place East and West of the two piers located at the Washington State Ferries Eagle Harbor Repair Facility. Work has commenced and will continue through September 1997. Five marker buoys with "KEEP OUT" signs on them will be positioned around the work area. There will be derrick barges and material barges on the project site for the duration of the project. Barge mooring lights will be displayed on corners of the barges at night. VHF-FM Channel 16 will be monitored during the working hours of 0700 to 1900, Monday through Friday. The call sign is "WPR5640".

Chart 18445, 18449 and 18474

## OREGON - ASTORIA - U.S. COAST GUARD AUXILIARY - Boating Safety and Seamanship Classes -

Boating Safety and Seamanship classes will be held at the U.S. Coast Guard Tongue point facility east Astoria off U.S. Hwy 30. Classes will be held each Tuesday and Thursday at 1900 local beginning 08 July, ending 14 August 1997. Instruction will include: Navigation rules, aids to navigation, boat handling and other practical subjects to boaters. Cost of instruction materials will be \$25.00 per person, \$30.00 per couple. Contact either Ken Carrel at (503)-861-9485 or Doug Cameron at (503)-325-2378 for preregistration.

#### OREGON - Marine Events - Portland Area -

AREA/LOCATION	DATE	TIME	<b>EVENT</b>	-	SPC	NSOR		PHONE	Ξ#	
Wilamette River Water	front Par	k	07/04/9	97	2200-2	230	Firewo	rks Displ	ay	Oregon
Food Bank 503-65	6-1999									
Wilamette River Oaks	Park	07/04/9	97	2200-2	230	Firewo	rks Disp	lay	Oaks	
Amusement Park	503-65	6-1999								
Columbia River Cascad	de Locks	07/04/9	97	2130-2	300	Firewo	rks Disp	lay	Port of	Cascade
Locks 541-379-8510										
Columbia River Sand Is	sland Ma	arine Par	·k	07/04/9	97	2200-2	300	Firewo	ks Disp	lay
St. Helens Jay	cees	503-39	7-9780							
Columbia River Columl	bia Park	07/04/9	97	2200-2	300	Firewo	rks Disp	lay	Kenne	vick C.
O. C. 800-722-1070										
Columbia River Howard	d Amon	Park	07/04/9	7	1000-1	800	Hydrop	lane Ra	ces	Tri-City
Watersport Assoc.	509-73	5-0130								
Columbia River Columl	bia Park	07/25-2	27/97	0700-1	800	Hydrop	lane Ra	ces	Tri-City	Water
Follies 509-547-2203										
Columbia River to Willa	amette R	iver	08/01/9	97	0900-1	600	Swim F	Relay	Swimm	ning
Against Current	503-52	4-7444								
Willamette River Willan	nette Pa	rk	08/17/9	97	0800-1	600	Sailing	Regatta	SW Po	rtland
Rotary 503-645-1999										

#### II. DISCREPANCIES - DISCREPANCIES CORRECTED

THE FOLLOWING AIDS TO NAVIGATION ARE NOT WATCHING AS ADVERTISED IN THE LIGHT LIST VOLUME VI, THIRTEENTH DISTRICT SECTION:

- Underlined text denotes new discrepancy since last I NM

NOTE: Mariners are cautioned that portions of missing structures may remain.

## **FEDERAL AIDS**

09275	Aid Nar	ne Status UMPQUA RIVE	Chart E R LB 6A	BNM L	NM	OFF ST	ΓΑΤΙΟΝ	18584	0604-
09285	23/97 1322-96	WINCHESTER 49/96	BAY HBF	RENTRA	NCE	DBN 1	MISSING		
09315	49/96	UMPQUA RIVE	R LIGHT	15		MISSIN	IG	18584	1329-
11310	21/97	GOVERNMENT	ISLAND	SOUTH	CH D	BN 1	SUBMERGED	18531	0555-
11315 97	21/97	GOVERNMENT	ISLAND	SOUTH	CH D	BN 2	SUBMERGED	18531	0623-
11320 97	21/97	GOVERNMENT	ISLAND	SOUTH	CH D	BN 3	SUBMERGED	18531	0623-
11325 0623-97		GOVERNMENT 21/97	ISLAND	SOUTH	CH D	BN 5	SUBMERGED		18531
-	21/97	GOVERNMENT	ISLAND	SOUTH	CH D	BN 7	SUBMERGED	18531	0623-
11335 0623-97		GOVERNMENT 21/97					SUBMERGED		18531
11340 0623-97		GOVERNMENT 21/97					SUBMERGED		18531
	0623-97	• .					SUBMERGED		
11350 0623-97		GOVERNMENT 21/97					SUBMERGED		18531
11355 0623-97		GOVERNMENT 21/97				-	SUBMERGED		18531
11360 0623-97		GOVERNMENT 21/97			СН D		SUBMERGED	40504	18531
	21/97	MC GUIRE ROO			CLLD	SUBME		18531	0623-
11370 0623-97		GOVERNMENT 21/97	ISLAND	3001H	CHD	DIN ∠ I	SUBMERGED		18531

## II. DISCREPANCIES - DISCREPANCIES CORRECTED (continued)

LL#	Aid Na	me Status	Chart BNI	M LNM					
12075		BONNEVILLE	POOL DAYB	EACON 55		SUBME	ERGED		18531
0640-97	7	25/97							
12130		BONNEVILLE	POOL BUOY	´ 69		SUBME	ERGED		18531
0641-97	7	25/97							
15190		WILLAPA BAY	<b>ENTRANCE</b>	BUOY 8		MISSIN	IG		18504
0036-97	7	02/97							
15585		POINT CHEHA	LIS RANGE	FRONT LI	GHT	<b>IMPRO</b>	PER CHARACT	ERISTI	2
18502	0430-9	7 15/97							
15615		<b>GRAYS HARB</b>	OR SOUTH F	REACH A F	RR LIGH	Γ	MISSING TOP	DAYBO	ARD
	18502	0416-97	15/97						
12745		LAKE UMATILI	LA BUOY 75		SUBME	RGED		18539	0646-
97	26/97								
12755		LAKE UMATILI	LA BUOY 77		SUBME	RGED		18539	0646-
97	26/97								
15965		JOHNS RIVER	DAYBEACC	N 3		DAYBO	DARDS MISSING	3	
18502	0536-9	7 20/97							
97 12755 97 15965	26/97 26/97	LAKE UMATILI LAKE UMATILI JOHNS RIVER	LA BUOY 75			RGED	DARDS MISSING	18539	

18850 LACONNER RANGE FRONT LIGHT 18 MISSING 18427

0198-95 08/95

19005 CAP SANTE DAYBEACON 3 DESTROYED 18427 0537-

97 20/97

20285 FORT PECK LAKE LIGHT G MISSING 00000 NONE

SENT 49/96

PRIVATE AIDS

LL# Aid Name Status Chart BNM LNM

17535 POINT HUDSON MARINA LIGHT TEMP DISCONTINUED

18441 0450-97 16/97

THE FOLLOWING AIDS TO NAVIGATION DISCREPANCIES HAVE BEEN CORRECTED SINCE THE LAST LOCAL NOTICE TO MARINERS:

FEDERAL AIDS

LL # Aid Name Status Chart BNM LNM

11075 WARRIOR ROCK REEF LIGHTED BUOY 4 WATCHING PROPERLY 18524

0664-97 25/97

13115 SNAKE RIVER BUOY 3 WATCHING PROPERLY 18545 0648-

97 24/97

13155 SNAKE RIVER BUOY 7 WATCHING PROPERLY 18545 0649-

97 25/97

#### II. DISCREPANCIES - DISCREPANCIES CORRECTED (continued)

#### **PRIVATE AIDS**

LL # Aid Name Status Chart BNM LNM

NONE

#### III. TEMPORARY CHANGES - TEMPORARY CHANGES CORRECTED

LEGEND: TRUB = Temporary Unlighted Buoy

TRLB = Temporary Lighted Buoy

TRLT = Temporary Light

# THE FOLLOWING AIDS TO NAVIGATION HAVE BEEN TEMPORARILY CHANGED:

LL # Aid Na	ame Status Chart BNM LNM				
09285	WINCHESTER BAY HBR ENTRANC	E DBN 1	TRUB	18584	1322-
96 49/96					
09315	UMPQUA RIVER LIGHT 15	TRLB	18584	1329-96	49/96
09520	SIUSLAW RIVER CHANNEL DBN 14	ļ	TRUB	18583	0238-
96 08/96					
09560	SIUSLAW RIVER CHANNEL DAYBE	ACON 26	TRUB		18583
0351-96	09/96				
09856	GARIBALDI CHANNEL LT 14	TRUB		18558 0953-9	)5
32/95					
11365	GOVERNMENT ISLAND SOUTH CH	DBN 19	TRUB		18531
0674-96	19/96				
16790	SHILSHOLE BAY BREAKWATER LI	GHT 3	SOUND SIGN	AL DISCONTINU	JED
18446 1315-	96 48/96				

THE FOLLOWING TEMPORARY AIDS TO NAVIGATION HAVE EITHER BEEN RESTORED TO NORMAL OPERATION OR DISCONTINUED:

LL# Aid Name Status Chart BNM LNM

18510 SNOHOMISH RIVER ENTRANCE RF LIGHT DISESTABLISHED 18444

0665-97

SNOHOMISH RIVER ENTRANCE RR LIGHT DISESTABLISHED 18515 18444

0665-97 04/95

#### IV. CHART CORRECTIONS

Corrective action affecting charts is contained in this section. Chart corrections are listed numerically by chart number. The correction listed pertains to that chart only. It is up to the mariner to decide what charts are to be corrected. The following example explains the individual elements of a typical correction.

Chart Cha	art Edition Last	: Local Notice			Source of	
Current Lo	cal					
number ed	dition date to N	<i>M</i> ariners		Datum	Correction	
Notice to M	<i>l</i> ariners					
 		I		1		
18555 3 <sup>rd</sup>	Ed. 1/16/97 Las	t LNM 01/97			NAD 83	(GS-95)
	02/97					,
W	A - FRANKLIN LA	KE - PROTECTION WA	TERWAY - SHE	LTER HAI	RBOR -	
(CGD13)						
` Ád	ld Safe Chann	el Light "2", FIR 4s 15F	T 4M		47248'30"N	
122215'00"		9				
I	1	1				
Docition	Corrective	Object of correctiv	e			
Position	action	action				

The letter (M) immediately following the chart number indicates that the correction should be applied to the metric side of the chart only. (Temp) indicates that the chart correction action is temporary in nature. Courses and bearings are given in degrees clockwise from 000 true. Bearings of light sectors are toward the light from seaward. The nominal range of lights is expressed in nautical miles.

18423 30<sup>th</sup> ed., 06/18/94 LAST LNM 20/97 NAD 83 WA - PUGET SOUND - (COD13)26/97

### BELLINGHAM TO EVERETT INCLUDING THE SAN JUAN ISLAND

Snohomish River Entrance Rear Range Light Delete 47259'52.5"N 122212'56.7"W Snohomish River Entrance Range Front Light

47259'27.5"N 122213'25.1"W

18434 4<sup>th</sup> ed., 04/27/96 LAST LNM 47/96 NAD 83 WA - SAN JUAN CHANNEL (CGD13)26/97 Fishermans Bay Buoy 8

48230'56.7"N 122254'55.7"W

18443 14<sup>th</sup> ed., 03/24/90 LAST LNM 08/97 NAD 83 WA - APPROACHES TO EVERETT (CGD13)26/97

Delete Snohomish River Entrance Rear Range Light

47259'52.5"N 122212'56.7"W

Snohomish River Entrance Range Front Light

47259'27.5"N 122213'25.1"W

18444 13<sup>th</sup> ed., 08/31/91 LAST LNM 08/97 NAD 83 WA - EVERETT HARBOR (CGD13)26/97

Delete Snohomish River Entrance Rear Range Light

47259'52.5"N 122212'56.7"W

Snohomish River Entrance Range Front Light

47259'27.5"N 122213'25.1"W

#### IV. CHART CORRECTIONS (continued)

18521 62<sup>nd</sup> ed., 02/03/96 LAST LNM 17/97 NAD 83 OR & WA - COLUMBIA RIVER -

(NOS CL-484/97)26/97

PACIFIC OCEAN TO HARRINGTON POINT

Add Controlling Depths for Entrance to Miller Sands Range

(See Enclosure 1)

18523 47<sup>th</sup> ed., 01/13/96 LAST LNM 21/97 NAD 83 OR - COLUMBIA RIVER - (NOS CL-484/97)26/97

#### HARRINGTON POINT TO CRIMS ISLAND

Add Controlling Depths for Miller Sands Range to Gull Island Turn and Channel

(See Enclosure 1)

18524 28<sup>th</sup> ed., 12/28/96 LAST LNM 18/97 NAD 83 OR - COLUMBIA RIVER - (NOS CL-484/97)26/97

(Side A) CRIMS ISLAND TO SAINT HELENS

Add Controlling Depths for Gull Island Turn and Channel to Saint

Helens Turn

(See Enclosure 2)

(Side B) (NOS CL-484/97)26/97

Add Controling Depths for Saint Helens Turn to Tomahawk Bar

(See Enclosure 2)

18526 50<sup>th</sup> ed., 12/28/96 LAST LNM 25/97 NAD 83 OR - PORT OF PORTLAND, (NOS CL-484/97)26/97

#### INCLUDING VANCOUVER

Add Controlling depth for Morgan Channel to Tomahawk Bar

(See Enclosure 3)

18531 18<sup>th</sup> ed., 02/19/94 LAST LNM 25/97 NAD 83 OR & WA - COLUMBIA RIVER -

(NOS CL-484/97)26/97

VANCOUVER TO THE DALLES

Add Controlling depth for Tomahawk Bar to Bonneville Locks

(See Enclosure 3)

(CGD13)26/97

5NM to Bonneville Pool Light 67

45236'35.7"N

121208'52.2"W

18533 10<sup>th</sup> ed., 03/31/90 LAST LNM 25/97 NAD 83 OR & WA - COLUMBIA RIVER -

(CGD13)26/97 LAKE CELILO

Relocate Maryhill-Biggs Bridge Approach B 36 from

(45<sup>2</sup>40'32.9"N, 120<sup>2</sup>50'6.0"W) to

45<sup>2</sup>40'33.9"N

120250'01.5"W

18545 13<sup>th</sup> ed., 03/03/90 LAST LNM 29/95 NAD 83 WA - SNAKE RIVER - LAKE SACAJAWEA

(CGD13)26/97

Relocate SNAKE RIVER BUOY 7 from

(46<sup>2</sup>14'19.1"N, 118<sup>2</sup>58'14.0"W) to

46214'19.6"N

118258'14.4"W

18587 66<sup>th</sup> ed., 08/19/95 LAST LNM 25/97 NAD 83 OR - COOS BAY

(NOS BPS-161019-161020)26/97

Add Controlling Depths for Coos Bay and Isthmus Slough

(See Enclosure 4)

18601 12<sup>th</sup> ed., 08/11/90 LAST LNM 25/97 NAD 83 OR - CAPE SEBASTIAN TO HUMBUG MT

(NOS CL-701/97)(CCGD)26/97

Change Rogue River Access Channel and Turning Basin Depth note to:

Shoaling to bare occurs seasonally, sometimes across the entire

width of the access channel, in the vicinity of the breakwaters.

The access channel controlling depth was 5 feet. The basin

42°27'45.0"N 124°22'35.0"W

controlling depth was 7 feet. April 1997

#### V. ADVANCE NOTICE OF CHANGES IN AIDS TO NAVIGATION

#### WASHINGTON - RICH PASSAGE -Buoyage -

During the month of July 1997, the bell will be removed from ainbridge Reef Lighted Bell Buoy 4 (LLNR 18030). No other changes will occur.

Chart 18441

#### VI. PROPOSED CHANGES IN AIDS TO NAVIGATION

Comments may be sent to the address on page one of this Local Notice to Mariners.

#### NONE

VII. GENERAL

REFER TO LOCAL NOTICE TO MARINERS 23/97 FOR CURRENT INFORMATION

## VIII. SUMMARY OF CORRECTIONS TO LIGHT LIST, VOLUME VI; PACIFIC COAST AND PACIFIC ISLANDS 1996:

(2) (1) (3)(4) (5) (6)(7) (8)No. Name and location Position Characteristic Ht Rng Structure Remarks Bonneville Pool 12125 - LIGHT 67 FI G 2.5s 21 5 SG on house. 26/97

### Marryhill-Biggs Bridge Approach

12340 - Buoy 36 45 40.5 Red nun.

120 50.0

• 26/97

# VIII. SUMMARY OF CORRECTIONS TO LIGHT LIST, VOLUME VI; PACIFIC COAST AND PACIFIC ISLANDS 1996: (continued)

(1) (2) (3) (4) (5) (6) (7) (8)

No. Name and location Position Characteristic Ht Rng Structure Remarks

Snohomish River

18510 - ENTRANCE RANGE FRONT Remove from list LIGHT

• 26/97

18515 - ENTRANCE RANGE REAR LIGHT 1063 yards, 037.42 from front light. Remove from list

#### 26/97

#### IX. ADDITIONAL ENCLOSURES:

1. Controlling Depths for Columbia River, Miller SandRnge to Gull Island Turn and Channel, Chart (18523) and for Columbia River Channel, Entrance to Miller Sands Range, Chart (18521)

- 2. Controlling Depths for Columbia River, Gull Island Turn and Channel to Sain $\mathbf{H}$ lelens Turn, Chart (18524) A and B
- 3. Controlling Depths for Morgan Channel to Tomahawk Bar, Chart (18526) and Tomahawk Bar **B**onneville Locks, Chart (18531)
- 4. Controlling Depths for Coos Bay and Isthmu\$lough, Chart (18587)
- 5. Waterway Analysis forQuillayute River, request for comment.

If you have any questions, comments, or need additional information concerning this or otheNMs or the LNM Mailing List (e.g. additions, deletions, corrections) contact the address or phone number on the front page.

### G. F. GREENE

Chief, Aids to I Thirteenth Coa	st Guard District	terways Management Branc	h	
COMMANDE NOTICE TO M	MARINERS NO. 2	COAST GUARD DISTRI		LOCAL
		NOTICE NO. 26		